


No 2 Cofferdam.

Sept. 10. 1930.


(35)



Midstream side of cofferdam
Water approx. 40ft below
river level outside. Leakage
confined & directed by
sandbags.

Sept. 29. 1930.

(36)



Upstream face of dam.
Sluice gate frames being
fitted in position.