

Feb 12<sup>th</sup> 1931.

Waitaki R. at Transmission Line Crossing.  
Main stream now on Otago side of river.

(104)



(105)



Protective islands on Otago side as shown on Photo (99)  
completely washed away and fast stream flowing  
through centre of foundations + behind groyne.  
In centre of cylinders a 10ft. hole was scoured out,  
this hole shingled up to 4ft. deep due to sandbag groyne.