

Sept. 8. 1933.

Main dam from Canterbury
abutment.

(181)




Part of village in background.

Compare with (59).

Dam near powerhouse
on Otago side of river

(182)



Two inspection galleries
in dam showing. 10 ton
Insley crane in new position.